



**HOLZ**  
Rubber Company, Inc.



# Sheave Liners

*Let us give you a lift!*

We have the widest selection of replacement sheave and bull wheel liners. Our time-tested liners will stretch your maintenance dollar.

## Sheave Liners Carried

- Doppelmayer®
- Poma of America®
- Riblet®
- Hall®
- Pomagalski®
- Ski Lift Int'l®
- Herron®
- Miner Denver®
- Tiegel®

## Holz Also Provides Quality

- **Bull Wheel Liners** (*Contact Holz for Tooling Availability*)
- Rubber Extrusions
- Custom Products



Lodi, CA 95241 USA  
Phone: 209-368-7171  
Fax 209-368-3246  
[www.holzrubber.com](http://www.holzrubber.com)  
[sales@holzrubber.com](mailto:sales@holzrubber.com)

## Holz Replacement Sheave Liners

Equipment Manufacturer	Description	Item Number	O.D.	Replacement Part Dimensions (in inches)	
				I.D.	Width
<b>Doppelmayr®</b>	Chair	644-02160	15.00	12.125	2.75
	Chair	420-00236*	15.00	12.125	2.75
	Chair	644-02286	10.12	7.68	2.68
	Chair	644-02287*	400 MM	320 MM	
	Chair	644-02288	381 MM	304 MM	
<b>Hall®</b>	Chair	644-02210	12.25	8.375	3.00
	Chair	644-02100	18.00	14.75	2.50
	559-1 Single Groove	644-02323	17.80	14.46	2.70
	569-1 Single Groove	644-02291	18.18	14.82	3.16
	569-3 Triple Groove	644-02292	18.18	14.82	3.16
	(PHB) Depression	644-02294	12.47	8.62	2.90
<b>Hjorath®</b>	Chair	644-02295	12.55	9.75	2.60
<b>Herron®</b>	Chair	644-02110	11.50	9.00	2.00
	Chair	644-02140	12.00	8.25	2.00
	Chair	644-02130	16.25	13.00	2.50
	Chair	644-02080	17.50	14.25	2.25
<b>Lift Engineers®</b>	M-3-4-02-05 Supportw/ Groove	655-34134	13.48	10.69	2.405
	M-3-04-02-04 Holdown w/Groove	655-34133	13.48	10.69	2.405
	S4	655-34132*	18.10	14.00	3.81
<b>Miner Denver®</b>	Chair	644-02125	21.00	18.00	2.50
<b>Mueller®</b>	Chair	644-02296	12.88	8.82	2.13
	Chair	644-02297	12.80	8.62	2.48
<b>PHB®</b>	Gondola Breakover	644-02298	12.67	8.41	2.50
	PHV(Hall) Depression	644-02299	12.47	8.62	2.90
	PHB Gondola Breakover	644-02301	15.90	12.58	2.10
<b>Poma®</b>	Chair	644-02302	12.50	9.38	2.38
	Quad 422 MM	644-02303	16.625	13.875	2.25
	Chair	644-02135	13.43	10.125	2.25
	Chair	644-02165	13.75	13.00	2.25
<b>Poma-Herron®</b>	Chair	644-02304	16.40	12.65	2.50
<b>Riblet®</b>	Breakover 1-1/8	644-02316	15.88	13.87	1.51
	Depression 1-1/8	644-02317	15.88	13.87	2.00
	Breakover 1-1/4	644-02318	15.88	13.86	1.80
	Depression 1-1/4	644-02319	15.88	13.86	2.33
	4073 1-5/8	644-02320	15.86	13.84	2.11
	4073 1-5/8 w/ Kevlar	644-02305	15.86	13.84	2.11
	14" Breakover w/Groove 1-1/4	644-02072			
	14" Depression w/Groove 1-1/8	644-02073			
	14" Depression w/Groove 1-1/4	644-02074			
	Chair	644-02152	20.25	18.50	2.25
<b>Robeling®</b>	Chair	644-02306	18.54	13.38	2.38
<b>Savio®</b>	Breakover	644-02307	12.75	9.85	2.40
	Gondola	644-02308	17.60	14.46	2.25
<b>Ski Lift International®</b>	Old Style Deep Groove	644-02121	15.00	11.625	3.125
	New Style	644-02060	15.00	11.625	3.125
	Chair	644-02325	15.34	11.70	3.17
<b>Stadeli®</b>	Chair	644-02309	11.25	8.23	1.80
	Chair	644-02310	13.15	9.57	1.94
	Chair	644-02311	12.67	9.55	1.92
<b>Tiegel®</b>	Chair	644-02127	10.00	8.00	1.50
	Chair	644-02004	17.50	14.00	2.25
<b>Yan®</b>	For 1-1/4 Rope	644-02120	13.48	10.69	2.405
<b>Yan/Lift Engineering®</b>	Chair	644-02315	13.75	10.75	2.50
	20" Gondola	644-02313	19.48	16.44	2.64
	Quad	644-02414*	18.00	13.90	3.80
	Quad	644-02314	9.85	6.08	3.16

## Holz Replacement Bull Wheel Liners

<b>Doppelmayr®</b>	Bull Wheel Liner	420-02285	2.87	1.06	10' Long / .44" Radius
<b>Lift Engineers®</b>	Bull Wheel Liner 1-61-2-0000-01C	420-11001			36'/40'/44" Lengths

**NOTE:** When requesting a quotation, please submit samples or a drawing. \* Denotes sheave liner with fabric.